



Post Office Box 3005
2831 Talleyrand Avenue
Jacksonville, Florida 32206-0005
www.jaxport.com

July 8, 2021

ADDENDUM NO. 02
TO
SPECIFICATIONS AND CONTRACT DOCUMENTS
FOR
INVITATION TO BID
BIMT BERTH 22 HIGH HEAVY LOT RESURFACING
JPA CONTRACT NO. C-1782

The item(s) of this Addendum shall modify and become a part of the contractual documents for this project as of this date. (Failure to acknowledge this addendum will be grounds for rejection of proposal.)

ATTACHMENTS TO CONTRACT SPECIFICATIONS

ATTACHMENT NO. 01

Response to Questions

Acknowledgment of the following addenda is hereby made:

Addendum #2, Dated: _____ Initials _____

Company _____

NOTE: THIS ADDENDUM SHALL BE ACKNOWLEDGED IN YOUR BID SUBMISSION, FAILURE TO ACKNOWLEDGE ADDENDUM WILL BE GROUNDS FOR REJECTION OF BID.

PLEASE VISIT <http://www.jaxport.com/procurement/active-solicitations> OR CALL THE PROCUREMENT DEPARTMENT AT (904) 357-3017, PRIOR TO THE BID OPENING TO DETERMINE IF ANY ADDENDA HAVE BEEN RELEASED ON THIS CONTRACT.



Post Office Box 3005
2831 Talleyrand Avenue
Jacksonville, Florida 32206-0005

REQUEST FOR QUALIFICATIONS

JPA CONTRACT NO.: C-1782 BIMT BERTH 22 HIGH HEAVY LOT RESURFACING

RESPONSE TO QUESTIONS

1. Is there an Engineer's estimate for the project?

ANSWER: Estimated budget is \$180,000

2. Is the asphalt for the pot hole repairs also to be SO 19.0mm with high polymer binder?

ANSWER: Yes.

3. For Option #1 area, will the fence need to be taken down and replaced? If not, there will be a narrow strip of existing asphalt remaining due to equipment being unable to access at least 6" on each side of fence.

ANSWER: If Option # 1 is executed, Jaxport will remove and re-install the fence.

4. Does JAXPORT have a list of preferred carriers so I can be sure I'm in compliance with potential contractual agreements?

ANSWER: No.